

Appendix A
Photographs of Woodstoves

Contents of Appendix A

Each stove involved in the study was inspected and photographed to document the stove's condition and installation. A photograph of each stove is presented in this appendix. For those stoves that showed degradation or had replacement parts, additional photographs documenting the stove's condition have been included.

Klamath Falls Photographs

Photograph

1	KF01. Non-Catalytic Quadrafire 2100.	A-4
2	KF01. Displaced Ceramic Blanket in the Non-Catalytic Quadrafire 2100.	A-5
3	KF02. Non-Catalytic Pacific Energy Super 27	A-6
4	KF02. Replaced Smoke Baffle in the Non-Catalytic Pacific Energy Super 27.	A-6
5	KF03. Non-Catalytic Haughs 171E.	A-7
6	KF03. Cracks in the Rear Secondary Air Ports in the Non-Catalytic Haughs 171E. .	A-7
7	KF04. Catalytic Earthstove 1003c.	A-8
8	KF05. Non-Catalytic Pacific Energy Super 27.	A-8
9	KF05. Degraded Baffle and Ceramic Blanket in the Non-Catalytic Pacific Energy Super 27.	A-9
10	KF06. Non-Catalytic Waterford MKII.	A-10
11	KF06. Degraded Baffle in the Non-Catalytic Waterford MKII.	A-11
12	KF07. Non-Catalytic Earthstove 1400HT.	A-12
13	KF07. Worn Refractory Elements in the Non-Catalytic Earthstove 1400HT.	A-12
14	KF07. Warped Secondary Inlet Tube in the Non-Catalytic Earthstove 1400HT. ...	A-13
15	KF08. Non-Catalytic Country T-Top.	A-13

Portland Photographs

Photograph

16	P01. Catalytic Trailblazer Genesis 2000.	A-14
17	P01. Cracked Baffle in the Catalytic Trailblazer Genesis 2000.	A-14
18	P01. Degraded Catalyst in the Catalytic Trailblazer Genesis 2000.	A-15
19	P02. Non-Catalytic Lopi Answer Series.	A-15
20	P02. Degraded Support for the Front Secondary Air Tube in the Non-Catalytic Lopi Answer Series.	A-16
21	P02. Creosote Deposits on the Secondary Air Tube in the Non-Catalytic Lopi Answer Series.	A-16
22	P03. Non-Catalytic Lopi 380-96.	A-17
23	P04. Catalytic Flush Bay-96 (Now Freedom).	A-18
24	P04. Warped and Flaking Secondary Air Tube in the Catalytic Flush Bay-96.	A-18
25	P05. Catalytic Lopi Flex-95.	A-19
26	P05. Disturbed Catalyst Interam Seal in the Catalytic Flex-95.	A-19
27	P06. Non-Catalytic Pacific Energy Super 27.	A-20
28	P06. Sagging Baffle in the Non-Catalytic Pacific Energy Super 27	A-21
29	P07. Non-Catalytic Lopi 520-96.	A-21
30	P07. Flaking Secondary Air Tube in the Non-Catalytic Lopi 520-96.	A-22
31	P08. Catalytic Vermont Castings Defiant Encore.	A-22



Photograph 1
KF01. Non-Catalytic Quadrafire 2100.



Photograph 2
KF01. Displaced Ceramic Blanket in the Non-Catalytic Quadrafire 2100




Photograph 3
KF02. Non-Catalytic Pacific Energy Super 27.



Photograph 4
KF02. Replaced Smoke Baffle in the Non-Catalytic Pacific Energy Super 27.



Photograph 5
KF03. Non-catalytic Haughs 171E.



Photograph 6
KF03. Cracks in the rear secondary air ports in the non-catalytic Haughs 171E.



Photograph 7
KF04. Catalytic Earthstove 1003C.




Photograph 8
KF05. Non-catalytic Pacific Energy Super 27.



Photograph 9
KF05. Degraded baffle and ceramic blanket in the non-catalytic Pacific Energy Super 27.



Photograph 10
KF06. Non-catalytic Waterford MKII.




Photograph 11
KF06. Degraded baffle in the non-catalytic Waterford MKII.



Photograph 12
KF07. Non-catalytic Earthstove 1400HT.



Photograph 13
KF07. Worn refractory elements in the non-catalytic Earthstove 1400HT.



Photograph 14
KF07. Warped secondary inlet tube in the non-catalytic Earthstove 1400HT.



Photograph 15
KF08. Non-catalytic Country T-Top.